



Manufacturers Identification

CATACHEM, INC.
955 Connecticut Avenue, Suite 4106
Bridgeport, Connecticut, 06607 USA
Ph: (203) 335-9277
Fax: (203) 335-9977
Email: catachem@catacheminc.com

Material Identification And Information

Components: Water, Sodium hydroxide

Physical /Chemical Characteristics

Boiling Point: N/A
Specific Gravity: N/A
Appearance and Odor: Clear colorless liquid. Soluble in water.

Fire And Explosion Hazard Data

Extinguishing Media: Water
Special Fire Fighting Procedures: Any means suitable for extinguishing supporting fire.
Unusual Fire and Explosion Hazards: Not considered to be an explosion hazard. Hazardous polymerization will not occur.

Reactivity Hazard Data

Stability: Stable
Incompatibility (Materials to Avoid): Keep out of contact with metals and reducing material.
Hazardous Decomposition Products:

Health Hazard Data

Effects of Overexposure: May cause irritation if inhaled, ingested or absorbed into skin.
First Aid Procedures: In case of contact with skin or eyes, remove contaminated clothing and shoes. Wash affected area with copious amounts of water. Assure adequate flushing of eyes by separating eyelids with fingers. Call a physician. If inhaled, remove to fresh air. If ingested drink large amounts of water or milk. Call a physician.
Emergency First Aid Procedures: Seek medical assistance for further treatment, observation and support if necessary.

Control And Protective Measures

Eye Protection: protective glasses
Protective Gloves: rubber or latex
Ventilation to be Used: local exhaust
Other Protective Clothing and Equipment: lab coat

Precautions For Safe Handling And Use/Spill/Leak Procedures

If Material is Spilled or Released: Mix with sodium bicarbonate and wash thoroughly with strong soap solution.
Waste Disposal Methods: Dispose waste according to local, state and federal regulation.
Precautions for Handling and Storage: Store in cool place, isolated from flammable material and away from heat or light.
Wash well after handling.

The above information is believed to be correct, but does not purport to be all inclusive and shall be used only as a guide. Catachem shall not be held liable for any damage resulting from handling or from contact with the above product. For technical assistance please call: 203-335-9277.



Manufacturers Identification

CATACHEM, INC.
955 Connecticut Avenue, Suite 4106
Bridgeport, Connecticut, 06607 USA
Ph: (203) 335-9277
Fax: (203) 335-9977
Email: catachem@catacheminc.com

Material Identification And Information

Components: Water, Picric Acid

Physical /Chemical Characteristics

Boiling Point: N/A
Specific Gravity: N/A
Appearance and Odor: Yellow, odorless. Soluble in water.

Fire And Explosion Hazard Data

Extinguishing Media: Water
Special Fire Fighting Procedures: Any means suitable for extinguishing supporting fire.
Unusual Fire and Explosion Hazards: Not considered to be an explosion hazard. Hazardous polymerization will not occur.

Reactivity Hazard Data

Stability: Stable
Incompatibility (Materials to Avoid): Keep out of contact with metals and reducing material.
Hazardous Decomposition Products:

Health Hazard Data

Effects of Overexposure: May cause irritation if inhaled, ingested or absorbed into skin.
First Aid Procedures: In case of contact with skin or eyes, remove contaminated clothing and shoes. Wash affected area with copious amounts of water. Assure adequate flushing of eyes by separating eyelids with fingers. Call a physician. If inhaled, remove to fresh air. If ingested drink large amounts of water or milk. Call a physician.
Emergency First Aid Procedures: Seek medical assistance for further treatment, observation and support if necessary.

Control And Protective Measures

Eye Protection: protective glasses
Protective Gloves: rubber or latex
Ventilation to be Used: local exhaust
Other Protective Clothing and Equipment: lab coat

Precautions For Safe Handling And Use/Spill/Leak Procedures

If Material is Spilled or Released: Mix with sodium bicarbonate and wash thoroughly with strong soap solution.
Waste Disposal Methods: Dispose waste according to local, state and federal regulation.
Precautions for Handling and Storage: Store in cool place, isolated from flammable material and away from heat or light.
Wash well after handling.

The above information is believed to be correct, but does not purport to be all inclusive and shall be used only as a guide. Catachem shall not be held liable for any damage resulting from handling or from contact with the above product. For technical assistance please call: 203-335-9277.